



## Riverbanks Zoo and Garden



# Gift Shop, Guest Services and Grizzly/Otter Exhibit



## RIVERBANKS ZOO AND GARDEN

ENTRY PLAZA AND EXHIBITS:
GIFT SHOP, GUEST SERVICES, AND GRIZZLY & OTTER EXHIBIT

03.23-13.27

2015







## View of Restroom Building from the Northwest









## Tile Installation Progresses for the Restroom Interior









#### View of the Guest Services Building from the Northeast









## Trespa Panel Installation at the Guest Services Continues










## Interior Finishes, Ceilings and Lighting Progress at Guest Services









## Placement of Exterior Concrete Stairs and Ramp at Otter Holding









## **Moat Between Otter and Grizzly Exhibits Commences**









## **Otter Exhibit Pool Testing Begins**









## **Grizzly Exhibit Pool and Hardscape Takes Shape**










## Repainting of Existing Rockwork at Grizzly Exhibit Begins










## Viewing Steps Take Shape at Viewing Window into Otter Exhibit









## View of Otter Exhibit Pool from Inside Viewing Shelter









## **Grizzly Viewing Shelter Slab on Grade Preparations**









## View of the Gift Shop LSS Building from the West









## **Drywall Finishing and Duct Progresses Inside Gift Shop**









## Following Quickly Behind Drywall is First Coat of Paint









#### Ceiling Grid and Lighting Progresses at the Gift Shop









## Plumbing Piping Continues Inside of SSL LSS Building









## LSS Piping Progresses Inside and Out of LSS Building









## Roof Access Ladders Arrive for the Gift Shop LSS Building









#### CIP Wall Placement Continues at Phase II, Viewing Building









#### LSS Piping to be Coordinated with Backfill and Waterproofing









#### CIP Wall Placement Continues at Phase II, Holding Building





## One Week Look Ahead

**Boulders and Deadfall Trees to be** placed within the Exhibits next week. Painting the exhibit rockwork to progress at Grizzly; while the Moat and Pools continue to take shape for both Exhibits. Ceiling grid installation to continue at Gift Shop. Fire Alarm Installation to begin at the Restroom Building, while Fire **Alarm Testing commences at Guest** Services and Gift Shop Buildings. **Underground LSS piping to** continue to progress. Phase II concrete placement to drive forward at Viewing, Holding and Exhibit Walls. Backfill and Waterproofing to be coordinated with LSS Piping.









#### YOUR NEW GRIZZLY AND OTTER EXHIBITS COMING SOON



RIVERBANKS 200 & GARDEN Celebrating 40 Wild Years

RODGERS
Our Passion is Building\*





Jumper
Carter
Sease
ARCHITECTS