

Riverbanks Zoo and Garden

Gift Shop, Guest Services and Grizzly/Otter Exhibit



RIVERBANKS ZOO AND GARDEN

ENTRY PLAZA AND EXHIBITS:
GIFT SHOP, GUEST SERVICES, AND GRIZZLY & OTTER EXHIBIT

View of the Restroom Building from the Northeast



Restroom Building Ready For Final Architectural Inspection



Subgrade and Compaction Prior to Hardscaping Behind Otter Holding



View of the Guest Services Building from the Northeast



View of the Guest Services Building from the Southeast



Main Entrance Gate and Ticket Tacking Structure Underway



Interior Finishes Continue at The Guest Services Building



Interior Finishes Continue at The Guest Services Building



Otter LSS Equipment Installed and Commissioning Completed



View of the Gift Shop Building from the Southwest



Interior of the Gift Shop Building



View of the New Entrance Plaza From Inside of the Zoo




View of the Otter Exhibit Shelter from the South



View of the Grizzly Life Support Cave and Softscape



View of the Grizzly Viewing Cave with Ecos Signage




Interior of the Otter Viewing Shelter with Ecos Signage



Interior of the Grizzly Viewing Shelter and Ecos Signage



View from Inside the Grizzly Bear Exhibit



View of the Exhibit Shelter from Inside of Grizzly Bear



View of the Stream and Shelter from Inside of Grizzly



View from Inside of the Otter Exhibit



View from Inside of the Otter Exhibit



View of the Otter Exhibit from Above



View of the Grizzly Bear Exhibit from Above



Life Support Building and New Chiller Courtyard



SSL LSS Equipment Installation Continues



Large SSL Pumps Being Assembled Inside the LSS Room



Protein Fractionator Installation Underway



New Construction Entrance Gate



Temporary Road Between the Existing Bird and LSS Buildings



Holding Building CIP Wall Placement Underway



CIP Walls and LSS Piping Being Placed Around the Exhibit Pool



Entrance and Lower Level Viewing Slabs On Grade Placed



One Week Look Ahead

Final Architectural and Owner Inspection of the Exhibits and Restrooms are scheduled for next week. The Zoo has moved the Otters into Otter Holding this week, with both the Otters and Grizzly Bears to be introduced to their new exhibits by the end of next week. Architectural and Owner Punch Out for the Guest Services and Gift Shop Buildings scheduled for next week. Wood Decking and Ice and Water Shield to be installed at the Entry Gate Structure; along with measurements, for the Standing Seam Steel Roof. Hardscape to continue to progress behind the Guest Services and at the Entry Gate Structure. Concrete Pad Placement for Phase II, Mock Up to begin. CMU to Steel Bearing and Grade at Phase II, Holding; with Beams and Columns to be set at SSL Viewing Building.



Our Passion is Building®

