

# Riverbanks Zoo and Garden RODGERS

Gift Shop, Guest Services and Grizzly/Otter Exhibit



### RIVERBANKS ZOO AND GARDEN

ENTRY PLAZA AND EXHIBITS: GIFT SHOP, GUEST SERVICES, AND GRIZZLY & OTTER EXHIBIT

> 05.25-05.29 **2015**





#### View of the Restroom Building from the Northeast







#### **Restroom Building Ready For Final Architectural Inspection**







#### Hardscaping Behind Otter Holding Changed from Asphalt to Concrete







#### View of the Guest Services Building from the Northeast







#### View of the Guest Services Building from the Southeast







#### Main Entrance Gate Continues to Take Shape







#### Interior Finishes Complete at The Guest Services Building







#### Interior Finishes Continue at The Guest Services Building







#### Otter LSS Equipment Installed and Commissioning Completed







#### View of the Gift Shop Building from the Southwest









#### Interior of the Gift Shop Building







#### View of the New Entrance Plaza From Inside of the Zoo







#### View of the Otter Exhibit Shelter from the South








#### View of the Grizzly Life Support Cave and Softscape







#### View of the Grizzly Viewing Cave with Ecos Signage










#### Interior of the Otter Viewing Shelter with Ecos Signage











#### Interior of the Grizzly Viewing Shelter and Ecos Signage







#### View from Inside the Grizzly Bear Exhibit








#### View of the Exhibit Shelter from Inside of Grizzly Bear








#### View of the Stream and Shelter from Inside of Grizzly








#### View from Inside of the Otter Exhibit








#### View from Inside of the Otter Exhibit







#### View of the Otter Exhibit from Above







#### View of the Grizzly Bear Exhibit from Above







#### Chillers Delivered and Equipment Pads Placed at SSL LSS







#### SSL LSS Equipment Installation Continues







#### Large SSL Pumps Being Assembled Inside the LSS Room







#### **Protein Fractionator Installation Underway**







#### Phase II, Exhibit CIP Walls and LSS Underground Piping Progress







#### Holding Building CIP Wall Placement Underway







#### CMU Walls for Phase II, Holding Building Underway







## **One Week Look Ahead**

Final Architectural and Engineering Punch Lists have been developed for Phase I, Buildings: Restroom, Guest Services, Gift Shop and Exhibits; with those items to be completed by the end of next week. Hardscaping around Phase I, Buildings to continue

to progress next week; as the Entry Gate Structure takes shape. The Otters have been acclimating to their new environment this week, with the Grizzly Bears arriving this weekend. Completion of the Foundation Waterproofing and Backfilling of Phase II, Exhibit Walls scheduled for next week. Elevated Slabs and Walls to be placed at the Viewing Building. Structural Steel to be placed the following week at Holding.





Our





RODGERS

#### YOUR NEW GRIZZLY AND OTTER EXHIBITS COMING SOON

